

Message

From: Nonresponsive based on revised scope
Sent: 10/11/2019 9:45:04 PM
To: Wagner, Christine [Wagner.Christine@epa.gov]
Subject: Re: [EXT]Fwd: Shiloh Church / 3-5467[3061459]

We can but the volume of soil and suspected volume of debris in mound 5 would fit into the debris pile. If no debris we change? The pcb is high in half of mound 5.

The drum area excavated soil staging area. R u thinking 9W area?

Almost time to start the 2 day vacation.

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: "Wagner, Christine" <Wagner.Christine@epa.gov>
Date: 10/11/19 17:35 (GMT-05:00)
To: Nonresponsive based on revised scope
Subject: [EXT]Fwd: Shiloh Church / 3-5467[3061459]

CAUTION This email originates from a source outside the company. Please use caution when opening attachments, clicking on links, or following the senders request.

Nonresponsive based on revised scope

Mound 5 has PCBs but not RCRA metals. Shouldn't that be a separate waste stream?

We can discuss next week

Thank you

Chris

Begin forwarded message:

From: Nonresponsive based on revised scope
Date: October 11, 2019 at 12:28:38 PM EDT
To: "Wagner, Christine" <Wagner.Christine@epa.govmailto:Wagner.Christine@epa.gov>
Subject: Fwd: Shiloh Church / 3-5467[3061459]

Hi.

It looks like mound 5 (east/west) mound only has pub. Put that in the mound pile?

Mound 3 confirmation samples look great.

Enjoy the day

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: Nonresponsive based on revised scope
Date: 10/10/19 16:37 (GMT-05:00)
To: Nonresponsive based on revised scope
Subject: Shiloh Church / 3-5467[3061459]

The following reports are attached:

WO 3061459 , Work ID Shiloh Church / 3-5467 []

--- End Of List ---

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the

ED_013731B_00003285-00001

sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.